

Dunlap Lake

Edwardsville, Illinois

Water Testing Notes

August, 2010

The first round of testing was conducted on August 16, 2010.

Conditions: 3" rain during the same weekend; heavy debris in the lake due to storm water runoff

Location #1: Near the East Lake/ Gerber end of the lake where new box culverts were installed under East Lake

Location #2: Middle area of the dam

Location #3: Open lake area

The second round of testing was conducted on August 30, 2010.

Conditions: Sunny, hot and humid.

Locations: The area near the East Lake/ Gerber end of the lake where new box culverts were installed under East Lake was re-tested.

#1) BUOY

#2) BETWEEN BUOY AND CULVERT

#3) CULVERT 1

#4) CULVERT 2