

August 31, 2023

Carolyn Green Dunlap Lake Property Owners Association P.O. Box 5

Edwardsville, IL 62025 TEL: (618) 791-1398

FAX:

RE: Lake Water Dunlap Lake

Dear Carolyn Green:

TEKLAB, INC received 3 samples on 8/22/2023 10:05:00 AM for the analysis presented in the following report.

Samples are analyzed on an as received basis unless otherwise requested and documented. The sample results contained in this report relate only to the requested analytes of interest as directed on the chain of custody. NELAP accredited fields of testing are indicated by the letters NELAP under the Certification column. Unless otherwise documented within this report, Teklab Inc. analyzes samples utilizing the most current methods in compliance with 40CFR. All tests are performed in the Collinsville, IL laboratory unless otherwise noted in the Case Narrative.

All quality control criteria applicable to the test methods employed for this project have been satisfactorily met and are in accordance with NELAP except where noted. The following report shall not be reproduced, except in full, without the written approval of Teklab, Inc.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

Marvin L. Darling

Project Manager

(618)344-1004 ex 41

mdarling@teklabinc.com

Mowin L. Darling I



WorkOrder: 23081661

Illinois 100226 Kansas E-10374 Louisiana 05002 Louisiana 05003 Oklahoma 9978



Report Contents

http://www.teklabinc.com/

Client: Dunlap Lake Property Owners Association Work Order: 23081661
Client Project: Lake Water Dunlap Lake Report Date: 31-Aug-23

This reporting package includes the following:

Cover Letter	1
Report Contents	2
Definitions	3
Case Narrative	5
Accreditations	6
Laboratory Results	7
Receiving Check List	10
Chain of Custody	Appended



Definitions

http://www.teklabinc.com/

Client: Dunlap Lake Property Owners Association Work Order: 23081661

Client Project: Lake Water Dunlap Lake Report Date: 31-Aug-23

Abbr Definition

- * Analytes on report marked with an asterisk are not NELAP accredited
- CCV Continuing calibration verification is a check of a standard to determine the state of calibration of an instrument between recalibration.
- CRQL A Client Requested Quantitation Limit is a reporting limit that varies according to customer request. The CRQL may not be less than the MDL.
 - DF Dilution factor is the dilution performed during analysis only and does not take into account any dilutions made during sample preparation. The reported result is final and includes all dilution factors.
 - DNI Did not ignite
- DUP Laboratory duplicate is a replicate aliquot prepared under the same laboratory conditions and independently analyzed to obtain a measure of precision.
- ICV Initial calibration verification is a check of a standard to determine the state of calibration of an instrument before sample analysis is initiated.
- IDPH IL Dept. of Public Health
- LCS Laboratory control sample is a sample matrix, free from the analytes of interest, spiked with verified known amounts of analytes and analyzed exactly like a sample to establish intra-laboratory or analyst specific precision and bias or to assess the performance of all or a portion of the measurement system.
- LCSD Laboratory control sample duplicate is a replicate laboratory control sample that is prepared and analyzed in order to determine the precision of the approved test method. The acceptable recovery range is listed in the QC Package (provided upon request).
- MBLK Method blank is a sample of a matrix similar to the batch of associated sample (when available) that is free from the analytes of interest and is processed simultaneously with and under the same conditions as samples through all steps of the analytical procedures, and in which no target analytes or interferences should present at concentrations that impact the analytical results for sample analyses.
- MDL "The method detection limit is defined as the minimum measured concentration of a substance that can be reported with 99% confidence that the measured concentration is distinguishable from method blank results."
- MS Matrix spike is an aliquot of matrix fortified (spiked) with known quantities of specific analytes that is subjected to the entire analytical procedures in order to determine the effect of the matrix on an approved test method's recovery system. The acceptable recovery range is listed in the QC Package (provided upon request).
- MSD Matrix spike duplicate means a replicate matrix spike that is prepared and analyzed in order to determine the precision of the approved test method. The acceptable recovery range is listed in the QC Package (provided upon request).
- MW Molecular weight
- NC Data is not acceptable for compliance purposes
- ND Not Detected at the Reporting Limit
- NELAP NELAP Accredited
 - PQL Practical quantitation limit means the lowest level that can be reliably achieved within specified limits of precision and accuracy during routine laboratory operation conditions.
 - RL The reporting limit the lowest level that the data is displayed in the final report. The reporting limit may vary according to customer request or sample dilution. The reporting limit may not be less than the MDL.
 - RPD Relative percent difference is a calculated difference between two recoveries (ie. MS/MSD). The acceptable recovery limit is listed in the QC Package (provided upon request).
 - SPK The spike is a known mass of target analyte added to a blank sample or sub-sample; used to determine recovery deficiency or for other quality control purposes.
 - Surr Surrogates are compounds which are similar to the analytes of interest in chemical composition and behavior in the analytical process, but which are not normally found in environmental samples.
 - TIC Tentatively identified compound: Analytes tentatively identified in the sample by using a library search. Only results not in the calibration standard will be reported as tentatively identified compounds. Results for tentatively identified compounds that are not present in the calibration standard, but are assigned a specific chemical name based upon the library search, are calculated using total peak areas from reconstructed ion chromatograms and a response factor of one. The nearest Internal Standard is used for the calculation. The results of any TICs must be considered estimated, and are flagged with a "T". If the estimated result is above the calibration range it is flagged "ET"
- TNTC Too numerous to count (> 200 CFU)



Definitions

http://www.teklabinc.com/

Client: Dunlap Lake Property Owners Association Work Order: 23081661

Client Project: Lake Water Dunlap Lake Report Date: 31-Aug-23

Qualifiers

- # Unknown hydrocarbon
- C RL shown is a Client Requested Quantitation Limit
- H Holding times exceeded
- J Analyte detected below quantitation limits
- ND Not Detected at the Reporting Limit
 - S Spike Recovery outside recovery limits
 - X Value exceeds Maximum Contaminant Level

- B Analyte detected in associated Method Blank
- E Value above quantitation range
- I Associated internal standard was outside method criteria
- M Manual Integration used to determine area response
- R RPD outside accepted recovery limits
- T TIC(Tentatively identified compound)



Case Narrative

http://www.teklabinc.com/

Client: Dunlap Lake Property Owners Association

Work Order: 23081661

Client Project: Lake Water Dunlap Lake

Report Date: 31-Aug-23

Cooler Receipt Temp: 24.2 °C

Locations

	Collinsville		Springfield	Kansas City					
Address	5445 Horseshoe Lake Road	Address	3920 Pintail Dr	Address	8421 Nieman Road				
	Collinsville, IL 62234-7425		Springfield, IL 62711-9415		Lenexa, KS 66214				
Phone	(618) 344-1004	Phone	(217) 698-1004	Phone	(913) 541-1998				
Fax	(618) 344-1005	Fax	(217) 698-1005	Fax	(913) 541-1998				
Email	jhriley@teklabinc.com	Email	KKlostermann@teklabinc.com	Email	jhriley@teklabinc.com				
	Collinsville Air		Chicago						
Address	5445 Horseshoe Lake Road	Address	1319 Butterfield Rd.						
	Collinsville, IL 62234-7425		Downers Grove, IL 60515						
Phone	(618) 344-1004	Phone	(630) 324-6855						
Fax	(618) 344-1005	Fax							
Email	EHurley@teklabinc.com	Email	arenner@teklabinc.com						



Accreditations

http://www.teklabinc.com/

Client: Dunlap Lake Property Owners Association Work Order: 23081661

Client Project: Lake Water Dunlap Lake Report Date: 31-Aug-23

State	Dept	Cert #	NELAP	Exp Date	Lab	
Illinois	IEPA	100226	NELAP	1/31/2024	Collinsville	
Kansas	KDHE	E-10374	NELAP	4/30/2024	Collinsville	
Louisiana	LDEQ	05002	NELAP	6/30/2024	Collinsville	
Louisiana	LDEQ	05003	NELAP	6/30/2024	Collinsville	
Oklahoma	ODEQ	9978	NELAP	8/31/2023	Collinsville	
Arkansas	ADEQ	88-0966		3/14/2024	Collinsville	
Illinois	IDPH	17584		5/31/2025	Collinsville	
Iowa	IDNR	430		6/1/2024	Collinsville	
Kentucky	UST	0073		1/31/2024	Collinsville	
Missouri	MDNR	00930		5/31/2023	Collinsville	
Missouri	MDNR	930		1/31/2025	Collinsville	



Laboratory Results

http://www.teklabinc.com/

Client: Dunlap Lake Property Owners Association Work Order: 23081661

Client Project: Lake Water Dunlap Lake Report Date: 31-Aug-23

Lab ID: 23081661-001 Client Sample ID: Sample 1

Matrix: AQUEOUS Collection Date: 08/22/2023 9:05

Analyses	Certification	RL	Qual	Result	Units	DF	Date Analyzed Batch						
STANDARD METHODS 9223B 22ND ED., COLILERT-18 QUANTITRAY													
E Coli	IDPH	1.0		2.0	MPN/100ml	1	08/22/2023 12:14 R335383						
EPA 600 351.2													
Total Kjeldahl Nitrogen (as N)	NELAP	1	J	0.9	mg/L	1	08/24/2023 15:58 211228						
EPA 600 365.4 (TOTAL)													
Phosphorus, Total (as P)	NELAP	0.100		0.330	mg/L	1	08/24/2023 15:57 211227						
EPA 600 4.1.4, 200.7R4.4, META	LS BY ICP (TOTA	L)											
Lead	NELAP	0.0150		< 0.0150	mg/L	1	08/28/2023 10:09 211197						
SW-846 3510C, 8151A, CHLORIN	NATED HERBICID	ES BY GC/E	ECD										
2,4-D	NELAP	0.60		2.42	μg/L	2	08/28/2023 11:07 211211						
Surr: 2,4-Dichlorophenylacetic acid	d *	18.4-136		93.7	%REC	1	08/25/2023 16:18 211211						
Elevated reporting limit due to sample extract composition.													



Laboratory Results

http://www.teklabinc.com/

Client: Dunlap Lake Property Owners Association Work Order: 23081661

Client Project: Lake Water Dunlap Lake Report Date: 31-Aug-23

Lab ID: 23081661-002 Client Sample ID: Sample 2

Matrix: AQUEOUS Collection Date: 08/22/2023 9:15

Analyses	Certification	RL Qual	Result	Units	DF	Date Analyzed Batch
STANDARD METHODS 9223B 2	2ND ED., COLILE					
E Coli	IDPH	1.0	0	MPN/100ml	1	08/22/2023 12:14 R335383
EPA 600 351.2						
Total Kjeldahl Nitrogen (as N)	NELAP	1.0	1.1	mg/L	1	08/24/2023 16:00 211228
EPA 600 365.4 (TOTAL)						
Phosphorus, Total (as P)	NELAP	0.100	0.357	mg/L	1	08/24/2023 16:00 211227
EPA 600 4.1.4, 200.7R4.4, META	LS BY ICP (TOT	AL)				
Lead	NELAP	0.0150	< 0.0150	mg/L	1	08/28/2023 10:09 211197
SW-846 3510C, 8151A, CHLORI	NATED HERBICII	DES BY GC/ECD				
2,4-D	NELAP	0.30 J	0.29	μg/L	1	08/25/2023 16:44 211211
Surr: 2,4-Dichlorophenylacetic ac	id *	18.4-136	91.8	%REC	1	08/25/2023 16:44 211211



Client Project: Lake Water Dunlap Lake

Laboratory Results

http://www.teklabinc.com/

Client: Dunlap Lake Property Owners Association Work Order: 23081661

Report Date: 31-Aug-23

Lab ID: 23081661-003 Client Sample ID: Sample 3

Matrix: AQUEOUS Collection Date: 08/22/2023 9:25

Analyses	Certification	RL Qual	Result	Units	DF	Date Analyzed Batch						
STANDARD METHODS 9223B 22ND ED., COLILERT-18 QUANTITRAY												
E Coli	IDPH	1.0	2.0	MPN/100ml	1	08/22/2023 12:14 R335383						
EPA 600 351.2												
Total Kjeldahl Nitrogen (as N)	NELAP	1.0	1.0	mg/L	1	08/24/2023 16:03 211228						
EPA 600 365.4 (TOTAL)												
Phosphorus, Total (as P)	NELAP	0.100	0.379	mg/L	1	08/24/2023 16:02 211227						
EPA 600 4.1.4, 200.7R4.4, META	LS BY ICP (TO	ΓAL)										
Lead	NELAP	0.0150	< 0.0150	mg/L	1	08/28/2023 10:10 211197						
SW-846 3510C, 8151A, CHLORII	NATED HERBIC	IDES BY GC/ECD										
2,4-D	NELAP	0.30	ND	μg/L	1	08/25/2023 17:10 211211						
Surr: 2,4-Dichlorophenylacetic ac	id *	18.4-136	69.4	%REC	1	08/25/2023 17:10 211211						



Client: Dunlap Lake Property Owners Association

Receiving Check List

http://www.teklabinc.com/

Work Order: 23081661

Client Project: Lake Water Dunlap Lake Report Date: 31-Aug-23 Carrier: Doug Carney Received By: LM Completed by: Reviewed by: On: On: 22-Aug-23 22-Aug-23 Timothy W. Mathis Ellie Hopkins Extra pages included 0 Pages to follow: Chain of custody Shipping container/cooler in good condition? Yes **V** No 🗔 Not Present Temp °C 24.2 Type of thermal preservation? Ice 🗹 Blue Ice None Dry Ice Chain of custody present? **~** No 🗌 Yes Chain of custody signed when relinquished and received? **~** Yes No L **~** Chain of custody agrees with sample labels? No 🗀 Yes **~** Samples in proper container/bottle? Yes No 🗀 **V** Sample containers intact? Yes No Sufficient sample volume for indicated test? Yes **~** No **✓** No \square All samples received within holding time? Yes NA 🗸 Field Lab \square Reported field parameters measured: Yes 🗸 No 🗌 Container/Temp Blank temperature in compliance? When thermal preservation is required, samples are compliant with a temperature between 0.1°C - 6.0°C, or when samples are received on ice the same day as collected. No VOA vials ✓ Water - at least one vial per sample has zero headspace? Yes 🗌 No 🗀 No TOX containers Water - TOX containers have zero headspace? Yes No 🗌 Yes 🗹 No 🗌 Water - pH acceptable upon receipt? NA 🗸 NPDES/CWA TCN interferences checked/treated in the field? Yes No 🗀

Any No responses must be detailed below or on the COC.

pH strip #90719 TM. - TMathis - 8/22/2023 10:30:11 AM

E. Coli per project history. - MLDII/ERH 8/22/23

CHAIN OF CUSTODY pg. ___ of ___ Work order # 23081661

TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

												-						,								1 2 4					
Client:		Dunlap Lake Prop	perty Owne	ers As	sociation								S	am	ples	on:	X	ICE		BLU	E ICE		NO IC	E		<i>.</i> .	20	C	LTG#		5
Address:		P.O. Box 5											P	res	erve	d in		LAB	TQ.	FIEL	D			FC)RL	AB I	<u>JSE</u>	ONL	<u>.Y</u>		
City / State	e / Zip											Lab Notes: Tm 90719																			
Contact:	Carolyr	Carolyn Green Phone: (618) 791-1398								- E-Coli per projecthistery mulit 8/22/23																					
E-Mail:	carolyn	carolyn@dunlaplake.org Fax:									- E-Coli per projecthistery, mult 8/20/23 - Client Comments Please elmail results to doug. Carney @gmail. Com as well as Cardyn. Water temp of Site 1.85°F																				
Are these sample Are there any red	es known quired rep	to be involved in lito be hazardous? porting limits to be rition.	Yes met on the	X	No						×\(\frac{1}{2}\)		u	Ple	iase vell Ter	eu as te	rai Ca	l d	es 77 4	ut Sit	is to	- 8 · G	5°;	Ca F	irne	ey E	<u>></u> う'	Mai	l • C	0 W i	as
Carlo management consequence	ject Na	ame/Number	== tourimouse=140000000		Sample		lle	tor	's N	Var	ne			Ī	MAT	RIX					INDICATE ANALYSIS REQUESTED										
Lake Water	unla	PLake		1)	oueCarne	y														3											
Resul	ts Requ	uested	Billing	Inst	ructions	#	and	Ту	oe o	f Co	ntaiı	ners	§	1				١.		(4)44/3	7	2									
Standard		(100% Surcharge)					_	_		1			Aqueous					1,4-0	Cel	1 2 2	Pnospnorus	Ž									
Other	3 Da	y (50% Surcharge)] <u>Ş</u>	HNO3	H2S04					Suc				and a second	Ι΄	1		or US										
Lab Use Only	Sam	ple Identification	Date	/Time	1`	س	4		1							vii.voimine			1												
2308 iletel	Sample	e 1	1/22/	23	0905	2	1	1		T	T		Х				-	Х	X	X	X	Х					+				
UZ	Sample	2	8/22/		0915	2	1	1					х	†		1		Х	Х	X	Х	Х	1		-		+				
	Sample	3	8/22	123	0925	2	1	1				_	х	<u> </u>	$\dagger \dagger \dagger$	\top		Х	Х	Х	Х	Х			-	-	<u> </u>	1	 		
W3			,,		<u> </u>	十	\vdash			╅	_	╅	 	 	++		+-	 	-	<u></u>			<u> </u>	<u> </u>		-	+				
			_			┝	╁		-	-		+		-			-	-		navaturosees	10000000000000000000000000000000000000	ee produces	n deservations		· · · · · · · · · · · · · · · · · · ·			-	-	202202444	
Principal Viernice in Continue de la Viernice de la						┡	-			4	_	+	ļ	ļ				<u> </u>			******		-		ļ	-					***************************************
7-20 -00-00-00-00-00-00-00-00-00-00-00-00-0						Ļ					\perp	┸	<u></u>					<u></u>													
															100		-								-			www.			
							Π											Ī													
STATE OF THE PROPERTY OF STATE						T	Τ			1	T			<u> </u>			***********	NATIONAL PROPERTY.		***************************************		-	-	1	<u> </u>		\top				
25 AMERICAN DESCRIPTION DESCRI						十	H	Н		\dashv	+	+					+	-							LOZDSKI WOODN	***************************************	madamenam	пистомочном		AMADONAL	
	Palin	quished By		T		ᆣ	ate	/Tin				L		ļ	ll			<u>l</u> ecei	vod	D.,				<u> </u>	<u> </u>		<u> </u>	Date/1	Timo	<u> </u>	İ
À.,	T Carp	dalanea by			8/22			_		<u>()</u> ≥				_	20	W		ecei	veu	Dy					A.	77	12^{2}			00	
; Vice	7	X	·		012	-/	٧_	, ,	· W	<u> </u>			├ - (\supset	~ // /	· vy	3	•						+	0(4	<i>v_</i>			00	
**************************************	V	<u> </u>											 	***************************************										\perp							, ,
			-										_							********				+							
													ł																		